

Superior Warranty

Specific parts excluded

Extensive protection from the costs of sudden and unexpected failures.

✕ Body, paint, glass (including heated elements)

- Brightwork, interior and exterior trim

✕ Electrical wiring

- Wiring looms and harnesses

The effects of overheating

- Even if caused by a part included in this warranty

Cracked or porous cyclinder heads and blocks

- Burnt valves, carbon deposits, skimming and pressure testing

✕ Vehicle control systems

- Software malfunction or routine maintenance updates

✕ General parts

- Plugs; HT leads; brake and clutch frictional material; wiper blades/rubbers; auxiliary belts; hoses; pipes; light bulbs/units (including LED and Xenon); wheels and tyres; auxiliary or lead-acid batteries (12 & 24 volt); exhaust system; airbag and system; upgraded or revised software, firmware or any other aftermarket satellite navigation, media or communication equipment not fitted by the manufacturer

✕ Mechanical cables

- Clutch cable; fuel filler cap cable; charge port cover cable; handbrake cable; bonnet release cable; seat adjustment cables; window winder cable; door handle and lock cables

✕ General Exclusions

- “Good engineering practice” – If replacement of any component which has not suffered a mechanical failure is recommended, we will not pay for that replacement if only one part experiences a mechanical failure
- Damage to parts not included in this warranty or any resulting damage to the included parts
- Any repair, alteration or modification made to the vehicle outside of the manufacturer’s specification

Parts and repairs can get expensive



Alternator
£872.69



Clutch
£1,258.48



Water pump
£489.53



Differential
£3,784.24

The parts and labour estimates given are for illustrative purposes only and are based on replacement parts for a BMW 320TD M Sport 2020 and all costs include VAT. Prices correct at time of printing.